

# ASPEN DistriView™

## Version 10.3 Update

Please find enclosed the program CD for *ASPEN DistriView™* version 10.3. In this maintenance release we have fixed all the known bugs to date. This version has been tested under Windows 10.

You can use the enclosed CD to update an existing installation or to make a new installation.

Please write (support@aspeninc.com in English or soporte@aspeninc.com in Spanish or Portuguese) or call (650-347-3997) us if you have questions.

### **Bug fixes since Version 10.2**

- Right click on legend text box of transformer damage curve caused the program to crash. Fixed.
- The Network | Edit Node Area dialog box for assigning colors to equipment in different areas did not work under Windows 8. The 28 colors that should appear in the drop-down combo box showed up as all white. Fixed.
- By popular requests, we have restored the “Output to TTY Window” option for arc-flash analysis.
- Previous collection (PCC) files did not capture the Memo part of text annotations. Fixed.
- PCC files did not save the annotation attributes that are new in version 10: color, call-out, etc. Fixed.
- The stepped-event function did not work properly when there are reclosing lines. Fixed.
- The command to paste picture in OC window did not work. Fixed.
- The popup-menu command Remove Time Slider did not work. Fixed.
- The Paste function did not work. Fixed.
- The program did not update the line parameters correctly when line-table entry selection is changed in the line dialog box.
- We have improved the logic for importing relay data from manufacturer files.